

Incident Report - (Incident UID - IMF/TTK/KAR/INJ/25/00011)

Incident Information

Incident UID	IMF/TTK/KAR/INJ/25/00011	Category Name	Injury
Status	Final Report Released	Site Name	Elmore City
Department Name	Production	Incident Date & Time	26-Dec-2025 04:50:00 PM
Created On	27-Dec-2025 10:30:45 AM	Reported By	Fed Pollak

Incident Description

The operator was doing piercing on 16 T press. The component got stucked in the tool. While removing the component, the operator accidentally pressed the foot pedal and the stroke activated. Immediately he released his hand & laceration injury occurred.

Sections

Level of Injury	<input type="radio"/> L1-Bruise <input type="radio"/> L2-Abrasion <input type="radio"/> L3-Burn <input checked="" type="radio"/> L4-Laceration <input type="radio"/> L5-Fracture <input type="radio"/> L6-Amputation
------------------------	---

Photograph of injury & machine

: 0

Injury treatment details

Number of people injured:: 1	Treatment of Injury: Referred to Hospital for Treatment	Details of treatment given & doctor's advice:: Dressing apply and refer to external hospital
-------------------------------------	--	---

Injured person details

Name of the injured person: Viraj	Gender: Male	Role – ON / OFF: Off Roll	If Off role, mention the contractor name:: Star
Age: 22 Years	No. of Year's total experience in TTK Prestige : 04 month	No. of years in this process / machine : 04 month	Injury Happened in Which Shift? : General

Immediate Corrective Actions taken

Actions	Responsibility	Status	Completion date
Press operation training provided to all press operators.	Satyam	Completed	27-Dec-2025
Light curtain sensor shall be placed in the pinch point area	Satyam	Completed	27-Dec-2025

Investigation Team

Investigation Team

Fed Pollak

Incident History

Created On	Updated By	Comment	Attachments
02-Jan-2026 09:50:42 AM	Rocco Sanchez	Incident Status has been updated to 'FIRReleased'	
29-Dec-2025 09:48:54 AM	Mozell Heaton	Incident Status has been updated to 'Validated'	
29-Dec-2025 09:48:54 AM	Mozell Heaton	Description has been updated to 'The operator was doing piercing on 16 T press. The component got stucked in the tool. While removing the component, the operator accidentally pressed the foot pedal and the stroke activated. Immediately he released his hand & laceration injury occurred.'	

27-Dec-2025 10:30:46 AM	Fed Pollak	A new record was created: Site set to 'Karjan' Department set to 'Production' Process set to 'Piercing & Reviting' Asset set to 'Mechanical C Frame Press' Reported By set to 'Satyam Kumar' Type Of Incident set to 'Injury' Incident Description set to 'The operator was doing piercing on 16 T press. The component got stucked in the tool. While removing the component, the operator accidentally pressed the foot pedal and the stroke activated. Right hand thumb was got stucked in between the component and the tool. ' Incident Date Time set to '26-Dec-2025 04:50:00 PM' Status set to 'Submit'	
-------------------------	------------	--	--

Definition:

Injury Type	Level	Definition
Bruise	L1	Blood Clot
Abrasion	L2	Skin Rubbed with Rough Surface
Burn	L3	Skin Burn due to fire, chemical, etc
Laceration	L4	Tear or a cut in the skin
Fracture	L5	Bone Damage
Amputation	L6	Loss of body part