

Inspection Report - Cutting Machine Inspection Checklist (Inspection UID - I/MHC/GRR/CMI/26/00039)

Inspection Information

Inspection Type	Cutting Machine Inspection Checklist	Inspection Status	Approved
Site Name	Alanreed	Created on	18-Mar-2026 02:50:58 PM
Asset	Cutting Machine	Non Oqsha Assets	
Next Inspection Date	18-Apr-2026 02:50:58 PM	Next Inspection Overdue Days	0

Sections

Inspection checks

Company name: Guruleela Construction LLP	Contractor name: Krishna debnath
---	---

Attachments
Image

Equipment Status

Equipment Status at Site: In Site	Equipment Usage Status: In Usage
--	---

Check Points

1.Is machine body in good condition?: Yes	2.Is moving part of machine was properly guarded? (Ensure Guard provided by machine manufactures which is inbuilt is safe and sound and properly fitted): Yes	3.Is auto adjustable guard being in functional condition?: Yes	4.Is On/Off switch being in good condition without any damage?: Yes
5.Is cutting wheel free from defect, and rotating capacity was marked? (cutting wheel should be of standard quality only): Yes	6.Is positioning screw is in working condition and without any damage and can be used smoothly?: Yes	7.Is machine handle is good in condition?: Yes	8.Is power cable free from damage?: Yes
9.Is power connection has taken using industrial plug only?: Yes	10.Is there RPM of wheel is greater than motor wheel?: Yes	11.Is the suitable tool is using for fix the wheel?: Yes	12.Is using designed key only for changing cutting wheel?: Yes

Remarks

NA

Signatures

Inspected by: Krishna debnath at 18-Mar-2026 02:50 PM.	Checked by: Uma Mahesh Akki at 3/20/2026 12:40:47 PM.	Verified by: vaidya naik at 3/25/2026 9:58:24 AM.	Approved by: Nakka Phanindra Kumar EHS at 3/25/2026 10:03:13 AM.
---	--	--	---

Inspection History

Created On	Created By	Comment	Attachments
25-Mar-2026 03:33:13 PM	Caroline Su	Status has been updated to 'Approve'	
25-Mar-2026 03:33:12 PM	Caroline Su	Nakka Phanindra Kumar EHS has Approved.	
25-Mar-2026 03:28:24 PM	Loring Romero	vaidya naik has Verified.	
25-Mar-2026 03:28:24 PM	Loring Romero	Status has been updated to 'Verify'	
25-Mar-2026 03:28:24 PM	Loring Romero	Inspection has been assigned to Nakka Phanindra Kumar EHS at the Approved by stage.	
20-Mar-2026 06:10:47 PM	Owens Strauss	Uma Mahesh Akki has Checked.	
20-Mar-2026 06:10:47 PM	Owens Strauss	Status has been updated to 'Check'	
20-Mar-2026 06:10:47 PM	Owens Strauss	Inspection has been assigned to vaidya naik at the Verified by stage.	

18-Mar-2026 02:50:59 PM	Fidelia Real	A new record was created: Site set to 'Grava Residences' Asset Type set to 'Portable Electrical Tools' Inspection Type set to 'Cutting Machine Inspection Checklist' Status set to 'Inspection requested'	
18-Mar-2026 02:50:59 PM	Fidelia Real	Inspection has been assigned to Uma Mahesh Akki at the Checked by stage.	