

EHS INTERNAL AUDIT

Ref No.: PI/EHS/C/34
 Issue date: 05/05/25
 Rev No: 00

Inspection Information

Project Name		Blencoe		Location		
Assessor Name				Date		
SR. NO	PERFORMANCE AND STANDARDS	YES	NO	ACTION REQ.	DATE COM.	
1	1. There a first-aid kit on site,adequetly stocked and location, known by all the staffs?			No		
2	2. Is there a trained first aider on site?			No		
3	3. Is workmen well fare arrangements available in site?			No		
4	4. Are all the relevant important telephone numbers displayed?			No		
5	5. Prominently so that they are available 24 hrs a day?			No		
6	6. Is there an adequate Gate Check process?			No		
7	7. Are there safe passages, ladder, scaffolds?			No		
8	8. Can the doors be locked and are they being locked after duty hours			No		
10	10. Do the ladders have adequate handholds at the landing place?			No		
11	11. Are all tools and equipment tagged for safe use?			No		
12	12. Is there proper access to the scaffold platform?			No		
13	13. Does the scaffold look safe visibly			No		
14	14. Is harness available and being used ?			No		
15	15. Is scaffolding safe tag being used?			No		
17	17. Is the main electrical distribution board in good condition?			No		
18	18. Is housekeeping found satisfactory ?			No		
19	19. Are constructions waste been segregated ?			No		
20	20. Has a suitable toilets been provided for the workers?			No		
23	23. Are workmen aware of company Golden rules?			No		
24	24. There all hsse documents maintaining in frequency basis.?			No		
25	25. Are all workmen aware of NMPI & incident reporting?			No		
Comments:						

Inspection History

Created On	Created By	Comment	Attachments
------------	------------	---------	-------------