



**Inspection Report - P&M - Chain Pulley Block Inspection Checklist (Inspection UID - I/GLTO/GRR/P-C/26/00001)**

**Inspection Information**

<b>Inspection Type</b>	P&M - Chain Pulley Block Inspection Checklist	<b>Inspection Status</b>	Inspection requested
<b>Site Name</b>	Alanreed	<b>Created on</b>	26-Mar-2026 05:05:06 PM
<b>Asset</b>	7124	<b>Non Oqsha Assets</b>	
<b>Next Inspection Date</b>	26-Apr-2026 05:05:06 PM	<b>Next Inspection Overdue Days</b>	0

**Sections**

**Inspection checks**

<b>Company name:</b> Galecto Inc.	<b>Contractor name:</b> Lula Lim
-----------------------------------	----------------------------------

<b>Attachments</b>
<a href="#">Image</a>

**Equipment Status**

<b>Equipment Status at Site:</b> In Site	<b>Equipment Usage Status:</b> In Usage
--	---

**Check Points**

<b>1.Is the chain pulley block is good condition &amp; working with TPI?:</b> Yes	<b>2.Is the chain is free from corrosion, defects, cracks, damage etc?:</b> Yes	<b>3.Is the hook point is in good condition? (not stretched more than 15% of its original shape):</b> Yes	<b>4.Are safety latch is working condition and placed into hook?:</b> Yes
<b>5.Is SWL (safe working load) is marked and visible?:</b> Yes	<b>6.Is all the rotating parts are covered?:</b> Yes	<b>7.Is sufficient lubrication has done?:</b> Yes	

**Rejection Criteria**

<b>1.Reject if chain is elongated more than 3% of its original length. IS 3832:</b> Yes	<b>2.Reject if there are cracks, nicks, corrosion, or twisted links. IS 3832:</b> Yes	<b>3.Reject if chain links show excessive wear at bearing points. IS 3832:</b> Yes	<b>4.Reject if sprocket teeth are broken, worn, or do not properly engage with the chain. IS 15560:</b> Yes
<b>5.Reject if the wheel is deformed or cracked. IS 15560:</b> N/A	<b>6.Reject if hook shows cracks, distortion, or nicks. IS 8610:</b> N/A	<b>7.Reject if there is excessive noise, rough movement, or damaged teeth. IS 15560:</b> N/A	<b>8.Reject if pulley fails to lift or hold the test load (typically 1.25–1.5x rated capacity). IS 3832:</b> N/A
<b>9.Reject if nameplate with rated capacity and ID is missing or illegible. IS 3832:</b> N/A			

**Signatures**

<b>Inspected by:</b> Lula Lim at 26-Mar-2026 05:05 PM.	<b>Checked by:</b> NA	<b>Verified by:</b> NA	<b>Approved by:</b> NA
--	-----------------------	------------------------	------------------------

**Inspection History**

<b>Created On</b>	<b>Created By</b>	<b>Comment</b>	<b>Attachments</b>
26-Mar-2026 05:05:06 PM	Lula Lim	Inspection has been assigned to Adalberto Kaufmann at the Checked by stage.	