

Inspection Report - P&M - Chain Pulley Block Inspection Checklist (Inspection UID - I/GLTO/GRR/P-C/26/00001)

Inspection Information


Inspection Type	P&M - Chain Pulley Block Inspection Checklist	Inspection Status	Checked
Site Name	Alanreed	Created on	01-Apr-2026 11:29:23 AM
Asset	7124	Non Oqsha Assets	
Next Inspection Date	01-May-2026 11:29:23 AM	Next Inspection Overdue Days	0
Due Date	01-May-2026		

Sections

Inspection checks

Company name: Galecto Inc.	Contractor name: Caroline Su
-----------------------------------	-------------------------------------

Attachments



Equipment Status

Equipment Status at Site: In Site	Equipment Usage Status: In Usage
--	---

Check Points

1. Is the chain pulley block is good condition & working with TPI?: Yes	2. Is the chain is free from corrosion, defects, cracks, damage etc?: No	3. Is the hook point is in good condition? (not stretched more than 15% of its original shape): No	4. Are safety latch is working condition and placed into hook?: Yes
5. Is SWL (safe working load) is marked and visible?: No	6. Is all the rotating parts are covered?: No	7. Is sufficient lubrication has done?: No	

Rejection Criteria

1. Reject if chain is elongated more than 3% of its original length. IS 3832: Yes	2. Reject if there are cracks, nicks, corrosion, or twisted links. IS 3832: No	3. Reject if chain links show excessive wear at bearing points. IS 3832: Yes	4. Reject if sprocket teeth are broken, worn, or do not properly engage with the chain. IS 15560: No
5. Reject if the wheel is deformed or cracked. IS 15560: Yes	6. Reject if hook shows cracks, distortion, or nicks. IS 8610: No	7. Reject if there is excessive noise, rough movement, or damaged teeth. IS 15560: Yes	8. Reject if pulley fails to lift or hold the test load (typically 1.25–1.5x rated capacity). IS 3832: No

9.Reject if nameplate with rated capacity and ID is missing or illegible. IS 3832:
No

Signatures

Inspected by: Caroline Su at 01-Apr-2026 11:29 AM.	Checked by: Fidelia Piatt at 4/1/2026 6:09:31 AM.	Verified by: NA	Approved by: NA
---	--	------------------------	------------------------

Inspection History

Created On	Created By	Comment	Attachments
01-Apr-2026 11:39:31 AM	Fidelia Piatt	Fidelia Piatt has Checked.	
01-Apr-2026 11:39:31 AM	Fidelia Piatt	Inspection has been assigned to Loring Romero at the Verified by stage.	
01-Apr-2026 11:29:24 AM	Caroline Su	Inspection has been assigned to Fidelia Piatt at the Checked by stage.	