

**Inspection Report - DCP Fire Extinguisher Inspection Checklist (Inspection UID - I/MHC/GRR/DFE/26/00045)**

**Inspection Information**

<b>Inspection Type</b>	DCP Fire Extinguisher Inspection Checklist	<b>Inspection Status</b>	Checked
<b>Site Name</b>	Alanreed	<b>Created on</b>	04-Feb-2026 03:38:58 PM
<b>Asset</b>	FE_DCP	<b>Non Oqsha Assets</b>	
<b>Next Inspection Date</b>	04-Mar-2026 03:38:58 PM	<b>Next Inspection Overdue Days</b>	28
<b>Due Date</b>	04-Mar-2026		

**Sections**

**Inspection checks**

<b>Company name:</b> My Home Constructions Private Limited	<b>Contractor name:</b> Nakka Phanindra Kumar EHS
--	---

<b>Attachments</b>
<a href="#">Image</a>

**Equipment Status**

<b>Equipment Status at Site:</b> In Site	<b>Equipment Usage Status:</b> In Usage
--	---

**Check Points**

<b>Is the extinguisher body free from dents, rust, or damage, compromising its structural integrity?:</b> Yes	<b>Is the label or marking legible, displaying the extinguisher type, operating instructions, and capacity?:</b> Yes	<b>Is the pressure gauge needle within the operable (green) range as per IS 2190: 2010?:</b> Yes	<b>Are the safety pin and tamper seal intact and securely in place?:</b> Yes
<b>Is the discharge hose free from cracks, kinks, or blockages?:</b> Yes	<b>Is the nozzle free from obstruction and securely attached?:</b> Yes	<b>Is the dry chemical powder in good condition, free from caking or hardening (per IS 15683: 2006)?:</b> Yes	<b>Is the extinguisher shaken gently during inspection to ensure powder flowability?:</b> Yes
<b>Is the extinguisher placed in a designated, easily accessible location?:</b> Yes	<b>Is the extinguisher location clearly marked with a sign indicating it is a fire safety equipment?:</b> Yes	<b>Is the extinguisher free from obstructions or barriers (per BOCW Act Rule 67)?:</b> Yes	<b>For hydrostatic testing, is the extinguisher within its test interval (usually 5 years for DCP extinguishers)?:</b> Yes

**Signatures**

<b>Inspected by:</b> Nakka Phanindra Kumar EHS at 04-Feb-2026 03:38 PM.	<b>Checked by:</b> Uma Mahesh Akki at 2/4/2026 10:29:49 AM.	<b>Verified by:</b> NA	<b>Approved by:</b> NA
---	---	------------------------	------------------------

**Inspection History**

Created On	Created By	Comment	Attachments
04-Feb-2026 03:59:49 PM	Owens Strauss	Uma Mahesh Akki has Checked.	
04-Feb-2026 03:59:49 PM	Owens Strauss	Status has been updated to 'Check'	
04-Feb-2026 03:59:49 PM	Owens Strauss	Inspection has been assigned to Kishanrao Poleni -MHC at the Verified by stage.	
04-Feb-2026 03:38:58 PM	Caroline Su	A new record was created: Site set to 'Grava Residences' Asset Type set to 'Safety equipment' Inspection Type set to 'DCP Fire Extinguisher Inspection Checklist' Status set to 'Inspection requested'	
04-Feb-2026 03:38:58 PM	Caroline Su	Inspection has been assigned to Uma Mahesh Akki at the Checked by stage.	