

Safety Alert Report

Organisation	Falcon's Beyond Global Inc. Warrants
Safety Alert UID	T/TTK/UAA/26/00178
Status	Assigned
DueDate	31-Mar-2026
Site	Mathiston
User Type	Employee
Department	Production
Reported By	Kenyatta Eaton
Mobile Number	+91 2000006600
Others Involved	NA
Category	Unsafe Act
Unit / Location / Line	unit 2, Assembly, bracket welding line
Description	The emergency exit sign light unit is not working. (Near the body ,lid welding line)
Safety Alert Image(s)	NA
Safety Alert Video(s)	NA
Safety Alert Audio(s)	NA
Safety Alert File(s)	NA
Created	25-Mar-2026 07:31:01 AM
Modified	25-Mar-2026 09:34:04 AM
	Question: Hazard Category Answer: Physical
	Question: Severity Answer: Medium
Safety Alert Checklist	Question: Alert Group Answer: Health & Safety Alert
	Question: Remarks by Evaluator Answer: The emergency exit sign light unit is not working. (Near the body ,lid welding line)
Assigned To	Zora Hamlet
Resolved On	NA

25-Mar-2026 07:31:01 AM - Kenyatta Eaton: A new record was created: Uid set to 'T/TTK/UAA/26/00178' Site set to 'Hosur' Reported By set to 'Vignesh P' Category set to 'Unsafe Act' Department set to 'Production'

Safety Alert History

25-Mar-2026 07:31:57 AM - Kenyatta Eaton updated the status to

25-Mar-2026 09:34:04 AM - Domenick Benedict: Safety Alert status updated to Assigned. Assigned To has been updated to 'Kotteswaran G' Due Date has been updated to '31-Mar-2026'

To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/248/69092>

This is a computer generated report. For queries please mail to contact@oqsha.com